



540008

Installation of the Ford Speed Sensor Plug



1. Remove the retaining clip from the speed sensor which holds the speedometer cable in place. Pull out the speedometer cable and make sure the stock O-ring remains in place. NOTE: without the O-ring the sensor will leak.



2. Insert the sensor plug in place of the speedometer cable and re-insert the retaining clip to keep it in place.



3. Refer to the main manual for wiring instructions to complete the VHX installation.

